Figure 3.2.2-6
OU III Building 96 Area
Extraction Well TVOC Concentrations

2010 BNL Groundwater Status Report