Figure 3.2.2-5
OU III Building 96 Area
Extraction Well TVOC Concentrations

2013 BNL Groundwater Status Report