Figure 3.2.1-5
OU III Building 96 Area
Extraction Well TVOC Concentrations

2015 BNL Groundwater Status Report