Figure 3.2.10-4
OU III Airport Groundwater Remediation System
TVOC Influent Concentrations

2015 BNL Groundwater Status Report