


Figure 3.0-2
 Historical Summary of VOC Mass Removed
 Environmental Restoration
 2001 BNL Groundwater Status Report



Note: Approximately 60 pounds of carbon tetrachloride were removed from the pump out of well 085-98 in January 1999. The treatment system began operation in October 1999.