

ESH Coordinators & Quality Representatives Meeting

Safety Topic

Rich Biscardi
January 16, 2008



SIXTY YEARS
OF DISCOVERY
1947-2007

BROOKHAVEN
NATIONAL LABORATORY




Electric Clock Shock Incident

- Back of clock (protective cover) broken
- Exposed leads
- Clock plugged into outlet

Photo of Clock (front)



Photo of Clock (rear)



Thumb Screw Missing

