Figure 3.2.5-4
OU III Western South Boundary Groundwater Remediation System
Cumulative VOC Mass Removed