

OMC Job Risk Assessment

This OHSAS document was printed on 4/13/2007 5:04:00 PM and is no longer an official copy. The revision can be verified on the HR OHSAS Web page: <http://www.bnl.gov/hr/OHSAS.asp>

Name(s) of Specific Application Risk Team Members: L. Cavaliere, T. Maugeri (Note: L. Cavaliere is the only employee in OMC performing these tasks)	Point Value → Parameter ↓	1	2	3	4	5
Job Title: Radiology Services Job Number or Job Identifier: JRA-05	Frequency (B)	≤once/year	≤once/month	≤once/week	≤once/shift	>once/shift
Job Description: Radiological examinations and X-Ray processing	Severity (C)	First Aid Only	Medical Treatment	Lost Time	Partial Disability	Death or Permanent Disability
Training Procedures List (Optional): Applicable Standard Operating Procedures:	Likelihood (D)	Very Unlikely	Unlikely	Possible	Probable	Multiple
Approved by: Dr. J. Falco Date: 3/5/2007 Rev. #: 1						
Stressors (if applicable, please list all)		Reason for Revision (if applicable):				Comments:

Activity	Hazard	Control(s)	Before Additional Controls					Control(s) Added to Reduce Risk	After Additional Controls					% Risk Reduction	
			Stressor	# of People A	Frequency B	Severity C	Likelihood D		Risk* AxBxCxD	Stressors	# of People A	Frequency B	Severity C		Likelihood D
Patient Positioning	Lifting patients and film cassettes	Correct lifting techniques per J. Gatz, MA, MAP	N	1	5	1	3	15							

OMC Job Risk Assessment

This OHSAS document was printed on 4/13/2007 5:04:00 PM and is no longer an official copy. The revision can be verified on the HR OHSAS Web page: <http://www.bnl.gov/hr/OHSAS.asp>

Activity	Hazard	Control(s)	Before Additional Controls					Control(s) Added to Reduce Risk	After Additional Controls					% Risk Reduction	
			Stressor	# of People A	Frequency B	Severity C	Likelihood D		Risk* AxBxCxD	Stressors	# of People A	Frequency B	Severity C		Likelihood D
Take X-ray	X-ray Radiation	Separate room – distance and shielding	N	1	4	2	1	8							
Film developing (darkroom)	Walking into objects	Safelight illumination	N	1	5	1	3	15							
Mixing developer or fixer	Chemical fumes	Proper ventilation (completed)	N	1	3	2	1	6							
Chemical disposal	Chemical fumes, listing	Proper ventilation and correct lifting techniques	N	1	3	2	3	18							

*Risk:	0 to 20	21 to 40	41-60	61 to 80	81 or greater
	Negligible	Acceptable	Moderate	Substantial	Intolerable