Lucia Gamba Project Manager

Brookhaven National Laboratory Community Advisory Council March 10, 2022









with Teaming Partners

Cabrera Services, Inc.
ICC Commonwealth
GEI














View looking northwest at the silencer excavation area backfilled and compacted (SEP21).







Completion of backfill and compaction looking west (SEP21).







Hydroseeding looking east (OCT21).








Wastewater from paint abatement project being transferred from temporary storage tanks to tanker trucks for disposal (DEC21).







View looking west of grass establishment (DEC21).







Wastewater tanks being removed off site (FEB22).





Final Closeout Report Status:

- The Draft Final Closeout Report was sent to the regulators on 16DEC21.
- Received comments from NYSDEC on 04FEB22 and EPA on 10FEB22.
- Responses to comments and a revised Closeout Report was sent to the regulators on 22FEB22.
- Received one follow-up comment from NYSDEC on 04MAR22 that was addressed on 08MAR22. Waiting on EPA acceptance of our responses to their comments.



Questions