


Sample Ladder Information Form

Ladder ID: 801-003		Ladder Location: B801 Upper Roof Transition	
			
Identified Hazard / Deficiencies:		Mitigation / Controls:	
1e	1) Side rails do not have good "grip ability"	1) Wear gloves while climbing ladder, do not use side rails, use ladder rungs for handhold.	
4f	2) The step across distance from the nearest edge of the ladder to the nearest edge of the structure is less than 2.5 inches	2) Situational Awareness, exercise caution when grasping the top rung, if present	
6a	3) The ladder way floor opening or platform is not protected by standard railings on all exposed sides	3) Situational Awareness – there may not be adequate fall protection once on platform	
6b	4) The passage through the railing is not protected with a swing gate or offset	4) Situational Awareness - be cognizant of where you are in relation to opening when working on the roof.	
6i	5) For ladders, the top of the step or rung is not level with the top of the access/egress level or landing platform served by the ladder	5) Situational Awareness – ensure footing is secure before moving onto or off of the platform.	

If ladder conditions are different from the ones identified, do not use the ladder and notify your supervisor.

Ladder Pre Use Inspection has been completed for this ladder use

Worker		Briefing Conducted By:			
NAME	LIFE #	NAME	LIFE #	DATE	*SIGNATURE

*Signature indicates that you understand the content of the ladder briefing, acknowledge the hazards and associated controls identified on the Job Safety Analysis (JSA) and required PPE have been given the opportunity to ask questions, provide feedback or raise concerns and have completed the applicable training requirements.