


P:\2016\BNLab\16-02 Environmental Protection Division\Task 18 2018 Annual GW Report\Report\2019-06-14\ACAD Figures\Fig_3-07-02 061419.dwg



TITLE:

FORMER LANDFILL
MONITORING WELL LOCATIONS

2018 BNL GROUNDWATER STATUS REPORT

DWN:	VT: HZ.:	DATE:	PROJECT NO.:
AJZ	—	06/14/19	—
CHKD:	APPD:	REV.:	NOTES:
WRD	RFH	—	—
FIGURE NO.:		3.7-2	