


P:\2016\BNLab\16-02 EPD\Task 18 2018 Annual GW Report\Report\2019-06-14\ACAD Figures\2019-09-09 revised\Fig_3-10-02_090919.dwg



ENVIRONMENTAL PROTECTION DIVISION

TITLE:

MONITORING WELL SAMPLING AND GEOPROBE LOCATIONS
 - 1,4-DIOXANE CHARACTERIZATION ALONG BNL SITE BOUNDARY

2018 BNL GROUNDWATER STATUS REPORT

DWN: AJZ	VT:HZ.: -	DATE: 06/14/19	PROJECT NO.: -
CHKD: DEP	APPD: DEP	REV.: 09/09/19	NOTES: -
FIGURE NO.:		3.10-2	