


P:\2016\BNLab\16-02 EPD\Task 25 2019 Annual GW Report\Report\2020-06-12\Figures\ACAD Figures\Fig_3-10-03_061220.dwg



TITLE:
**OU V SEWAGE TREATMENT PLANT
 MONITORING WELL RESULTS FOR
 1,4-DIOXANE**
 2019 BNL GROUNDWATER STATUS REPORT

| | | | |
|--------------|--------------|-------------------|-------------------|
| DWN: AJZ | VT:HZ.: - | DATE: 06/12/20 | PROJECT NO.: - |
| CHKD: WRD | APPD: DEP | REV.: - | NOTES: - |
| FIGURE NO.: | | 3.10-3 | |