

Table 3.2.15-2
OU III Chemical/Animal Holes Sr-90 Remediation System 2019 Extraction Well Pumping Rates

2019 BNL Groundwater Status Report

Operable Unit III - Pump and Treat				
Chem Holes Strontium-90 Remediation System (gpm)				
BNL Well No.	106-92	106-123	106-124	
Extraction Well	SR-90 EW-1	SR-90 EW-2	SR-90 EW-3	
Screen Int.				
elevation (ft. msl)	+40.5 to +25.5	+32.6 to +22.6	+27.6 to +17.6	Monthly
depth (feet)	23.5 to 38.5	35 to 45	35 to 45	Total
January	stand-by	stand-by	stand-by	0.00
February	stand-by	stand-by	stand-by	0.00
March	stand-by	stand-by	stand-by	0.00
April	stand-by	stand-by	stand-by	0.00
May	stand-by	stand-by	stand-by	0.00
June	stand-by	stand-by	stand-by	0.00
July	stand-by	stand-by	stand-by	0.00
August	stand-by	stand-by	stand-by	0.00
September	stand-by	stand-by	stand-by	0.00
October	stand-by	stand-by	stand-by	0.00
November	stand-by	stand-by	stand-by	0.00
December	stand-by	stand-by	stand-by	0.00
Annual Average (gpm)	stand-by	stand-by	stand-by	0.0

Notes:

Differences in averages due to rounding

Source: LTRA Project Manager

ft. msl = Elevation in feet referenced to mean sea level.

Elevations rounded to nearest foot

gpm - gallons per minute