

Summary of Lead Service Line Inventory

I. System Information

Water System Name	Brookhaven National Laboratory
PWS ID Number	5111891

II. Contact Information for Owner / Licensed Operator of Record Completing the Form

Contact Name	Christopher R. Bruno, P.E.
Contact Phone Number	(631) 344-8262
Contact Email Address	cbruno@bnl.gov

III. Summary of Inventory

Total Number of Service Lines in the Distribution System	326
Total Number of Identified Service Lines	326
Total Number of Lead Service Lines	0
Total Number of GSLRR	0
Total Number of Non-LSL	326
Total Number of Unknown Service Lines	0

Service Lines	Lead	GSL or GSLRR	Non-Lead	Unknown
PWS - Side Service Lines	0	28 GSL	298	0
Customer - Side Service Lines	0	28 GSL	298	0
Total Number of Service Lines in the Distribution System	0	0 GSLRR	326	0

Service Line Identification Methods

Identification Methods	PWS- Side SLs	Customer-Side SLs
Historical Records	231	0
Field Inspection	0	326
Customer Identification with Photo or other Verification	NA	0
Excavation	29	0
Sequential Sampling	0	0
Statistical Analysis/Predictive Model	0	0

IV. Inventory Availability - The inventory must be available to public

If 50,000 customers or greater: Posting the inventory online water system's website.	Not Applicable
If under 50,000 customers: Explain how to access the inventory	Posted on BNL website at the following link: https://www.bnl.gov/water/

V. Certifications

By submitting this form, I have verified and certify the information listed in this form is true and accurate to the best of my knowledge and belief.

Christopher R. Bruno, P.E.	Manager, Energy & Utilities Division	10/1/24
Name	Title	Date

Street Address	Town	Zip Code	Lead Gooseneck, Pigtail or Connector Currently Present?	Current Public Side SL Material ①	Was Public SL Material Ever Previously Lead?	Public SL Material Verification Method ①	Public SL Installation or Replacement Date	Public SL Size	Customer SL Material ①	Customer SL Material Verification Method ①	Lead Solder Present?	Building Type	POU or POE Treatment Present? ①	Customer SL Installation or Replacement Date	Customer SL Size	SL Category ①	Note
Building 30	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Business	No		Larger than 2"	Non-Lead	
Building 30	Upton	11973	Unknown	Galvanized	No	Records		1.5" < SL ≤ 2"	Galvanized	Field Inspection	Unknown	Business	No		1.5" < SL ≤ 2"	Non-Lead	
Building 50	Upton	11973	No	Plastic	No	Excavation		Larger than 2"	Plastic	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 97	Upton	11973	No	Known Other	No	Not Verified		Larger than 2"	Known Other	Field Inspection	Unknown	Business	No		Larger than 2"	Non-Lead	
Building 97	Upton	11973	No	Copper	No	Not Verified		1.5" < SL ≤ 2"	Copper	Field Inspection	Unknown	Business	No		1.5" < SL ≤ 2"	Non-Lead	
Building 98	Upton	11973	No	Known Other	No	Excavation		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 98	Upton	11973	No	Known Other	No	Excavation		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 98	Upton	11973	No	Copper	No	Excavation		1" < SL ≤ 1.5"	Copper	Field Inspection	No	Other including Multiuse	No		1" < SL ≤ 1.5"	Non-Lead	
Building 101	Upton	11973	No	Known Other	No	Excavation		Larger than 2"	Known Other	Field Inspection	No	Business	No		Larger than 2"	Non-Lead	
Building 101	Upton	11973	No	Known Other	No	Excavation		Larger than 2"	Known Other	Field Inspection	No	Business	No		Larger than 2"	Non-Lead	
Building 120	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Business	No		Larger than 2"	Non-Lead	
Building 120	Upton	11973	No	Copper	No	Records		1.5" < SL ≤ 2"	Copper	Field Inspection	Unknown	Business	No		1.5" < SL ≤ 2"	Non-Lead	
Building 129	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Business	No		Larger than 2"	Non-Lead	Building 129 is abandoned and planned to be demolished.
Building 129	Upton	11973	No	Copper	No	Records		1.5" < SL ≤ 2"	Copper	Field Inspection	Unknown	Business	No		1.5" < SL ≤ 2"	Non-Lead	
Building 153	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Multi Family	No		Larger than 2"	Non-Lead	
Building 153	Upton	11973	No	Copper	No	Records		Larger than 2"	Copper	Field Inspection	Unknown	Multi Family	No		Larger than 2"	Non-Lead	
Building 170	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Multi Family	No		Larger than 2"	Non-Lead	
Building 170	Upton	11973	No	Copper	No	Records		Larger than 2"	Copper	Field Inspection	Unknown	Multi Family	No		Larger than 2"	Non-Lead	
Building 179	Upton	11973	No	Copper	No	Records		1.5" < SL ≤ 2"	Copper	Field Inspection	Unknown	Business	No		1.5" < SL ≤ 2"	Non-Lead	
Building 257	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Multi Family	No		Larger than 2"	Non-Lead	
Building 257	Upton	11973	Unknown	Galvanized	No	Records		1.5" < SL ≤ 2"	Galvanized	Field Inspection	Unknown	Multi Family	No		1.5" < SL ≤ 2"	Non-Lead	
Building 258	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Multi Family	No		Larger than 2"	Non-Lead	
Building 258	Upton	11973	No	Copper	No	Records		Larger than 2"	Copper	Field Inspection	Unknown	Multi Family	No		Larger than 2"	Non-Lead	
Building 302	Upton	11973	Unknown	Galvanized	No	Not Verified		1.5" < SL ≤ 2"	Galvanized	Field Inspection	Unknown	Multi Family	No		1.5" < SL ≤ 2"	Non-Lead	
Building 303	Upton	11973	Unknown	Galvanized	No	Not Verified		1.5" < SL ≤ 2"	Galvanized	Field Inspection	Unknown	Multi Family	No		1.5" < SL ≤ 2"	Non-Lead	
Building 306	Upton	11973	Unknown	Galvanized	No	Not Verified		1.5" < SL ≤ 2"	Galvanized	Field Inspection	Unknown	Multi Family	No		1.5" < SL ≤ 2"	Non-Lead	
Building 307	Upton	11973	Unknown	Galvanized	No	Not Verified		1.5" < SL ≤ 2"	Galvanized	Field Inspection	Unknown	Multi Family	No		1.5" < SL ≤ 2"	Non-Lead	
Building 317	Upton	11973	Unknown	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 317	Upton	11973	No	Known Other	No	Excavation		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 321	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	Building 321 is planned to be demolished.
Building 321	Upton	11973	No	Galvanized	No	Excavation		Up to 1"	Galvanized	Field Inspection	Unknown	Other including Multiuse	No		Up to 1"	Non-Lead	
Building 325	Upton	11973	Unknown	Known Other	No	Not Verified		1.5" < SL ≤ 2"	Known Other	Field Inspection	Unknown	Multi Family	No		1.5" < SL ≤ 2"	Non-Lead	
Building 326	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 326	Upton	11973	No	Copper	No	Other		1.5" < SL ≤ 2"	Copper	Field Inspection	Unknown	Other including Multiuse	No		1.5" < SL ≤ 2"	Non-Lead	
Building 327	Upton	11973	No	Copper	No	Excavation		Up to 1"	Copper	Field Inspection	No	Multi Family	No		Up to 1"	Non-Lead	
Building 327	Upton	11973	No	Copper	No	Excavation		Up to 1"	Copper	Field Inspection	No	Multi Family	No		Up to 1"	Non-Lead	
Building 328	Upton	11973	No	Copper	No	Excavation		Up to 1"	Copper	Field Inspection	No	Multi Family	No		Up to 1"	Non-Lead	
Building 328	Upton	11973	No	Copper	No	Excavation		Up to 1"	Copper	Field Inspection	No	Multi Family	No		Up to 1"	Non-Lead	
Building 330	Upton	11973	Unknown	Galvanized	No	Not Verified		Up to 1"	Galvanized	Field Inspection	Unknown	Multi Family	No		Up to 1"	Non-Lead	
Building 331	Upton	11973	Unknown	Galvanized	No	Not Verified		1.5" < SL ≤ 2"	Galvanized	Field Inspection	Unknown	Multi Family	No		1.5" < SL ≤ 2"	Non-Lead	
Building 334	Upton	11973	Unknown	Galvanized	No	Excavation		1" < SL ≤ 1.5"	Galvanized	Field Inspection	Unknown	Multi Family	No		1" < SL ≤ 1.5"	Non-Lead	
Building 335	Upton	11973	Unknown	Galvanized	No	Not Verified		1.5" < SL ≤ 2"	Galvanized	Field Inspection	Unknown	Multi Family	No		1.5" < SL ≤ 2"	Non-Lead	
Building 339	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 348	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Business	No		Larger than 2"	Non-Lead	
Building 348	Upton	11973	No	Copper	No	Records		1.5" < SL ≤ 2"	Copper	Field Inspection	Unknown	Business	No		1.5" < SL ≤ 2"	Non-Lead	
Building 348	Upton	11973	No	Copper	No	Records		1.5" < SL ≤ 2"	Copper	Field Inspection	No	Other including Multiuse	No		1.5" < SL ≤ 2"	Non-Lead	
Building 349	Upton	11973	Unknown	Galvanized	No	Excavation		1.5" < SL ≤ 2"	Galvanized	Field Inspection	Unknown	Multi Family	No		1.5" < SL ≤ 2"	Non-Lead	
Building 350	Upton	11973	Unknown	Galvanized	No	Excavation		1.5" < SL ≤ 2"	Galvanized	Field Inspection	Unknown	Multi Family	No		1.5" < SL ≤ 2"	Non-Lead	
Building 351	Upton	11973	Unknown	Galvanized	No	Not Verified		1.5" < SL ≤ 2"	Galvanized	Field Inspection	Unknown	Multi Family	No		1.5" < SL ≤ 2"	Non-Lead	
Building 355	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Business	No		Larger than 2"	Non-Lead	Building 355 is abandoned and planned to be demolished.
Building 355	Upton	11973	Unknown	Copper	No	Records		1.5" < SL ≤ 2"	Copper	Field Inspection	Unknown	Business	No		1.5" < SL ≤ 2"	Non-Lead	
Building 356	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 356	Upton	11973	No	Copper	No	Records		1.5" < SL ≤ 2"	Copper	Field Inspection	Unknown	Other including Multiuse	No		1.5" < SL ≤ 2"	Non-Lead	
Building 356	Upton	11973	No	Copper	No	Records		1.5" < SL ≤ 2"	Copper	Field Inspection	Unknown	Other including Multiuse	No		1.5" < SL ≤ 2"	Non-Lead	
Building 359	Upton	11973	Unknown	Galvanized	No	Not Verified		1.5" < SL ≤ 2"	Galvanized	Field Inspection	Unknown	Multi Family	No		1.5" < SL ≤ 2"	Non-Lead	
Building 360	Upton	11973	No	Copper	No	Excavation		1.5" < SL ≤ 2"	Copper	Field Inspection	No	Multi Family	No		1.5" < SL ≤ 2"	Non-Lead	
Building 361	Upton	11973	Unknown	Galvanized	No	Not Verified		1.5" < SL ≤ 2"	Galvanized	Field Inspection	Unknown	Multi Family	No		1.5" < SL ≤ 2"	Non-Lead	
Building 362	Upton	11973	Unknown	Galvanized	No	Not Verified		1.5" < SL ≤ 2"	Galvanized	Field Inspection	Unknown	Multi Family	No		1.5" < SL ≤ 2"	Non-Lead	
Building 363	Upton	11973	Unknown	Galvanized	No	Not Verified		1.5" < SL ≤ 2"	Galvanized	Field Inspection	Unknown	Multi Family	No		1.5" < SL ≤ 2"	Non-Lead	
Building 364	Upton	11973	No	Copper	No	Not Verified		1.5" < SL ≤ 2"	Copper	Field Inspection	Unknown	Multi Family	No		1.5" < SL ≤ 2"	Non-Lead	
Building 365	Upton	11973	No	Copper	No	Not Verified		1.5" < SL ≤ 2"	Copper	Field Inspection	Unknown	Multi Family	No		1.5" < SL ≤ 2"	Non-Lead	
Building 371	Upton	11973	No	Copper	No	Records		1" < SL ≤ 1.5"	Copper	Field Inspection	Unknown	Single Family	No		1" < SL ≤ 1.5"	Non-Lead	
Building 373	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	School or Childcare	No		Larger than 2"	Non-Lead	
Building 373	Upton	11973	No	Copper	No	Records		1.5" < SL ≤ 2"	Copper	Field Inspection	No	School or Childcare	No		1.5" < SL ≤ 2"	Non-Lead	
Building 400	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Business	No		Larger than 2"	Non-Lead	
Building 412	Upton	11973	No	Known Other	No	Excavation		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 422	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 422	Upton	11973	Unknown	Galvanized	No	Not Verified		1.5" < SL ≤ 2"	Galvanized	Field Inspection	Unknown	Other including Multiuse	No		1.5" < SL ≤ 2"	Non-Lead	
Building 423	Upton	11973	No	Copper	No	Excavation		1.5" < SL ≤ 2"	Copper	Field Inspection	Unknown	Other including Multiuse	No		1.5" < SL ≤ 2"	Non-Lead	
Building 438	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Business	No		Larger than 2"	Non-Lead	
Building 438	Upton	11973	No	Copper	No	Records		1" < SL ≤ 1.5"	Copper	Field Inspection	No	Business	No		1" < SL ≤ 1.5"	Non-Lead	
Building 449	Upton	11973	Unknown	Copper	No	Records		Up to 1"	Copper	Field Inspection	Unknown	Other including Multiuse	No		Up to 1"	Non-Lead	Building 449 is supplied water from adjacent Building 461.
Building 452	Upton	11973	No	Known Other	No	Not Verified		Larger than 2"	Known Other	Field Inspection	No	Business	No		Larger than 2"	Non-Lead	
Building 452	Upton	11973	Unknown	Copper	No	Records		1" < SL ≤ 1.5"	Copper	Field Inspection	Unknown	Business	No		1" < SL ≤ 1.5"	Non-Lead	
Building 459	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	Unknown	Business	No		Larger than 2"	Non-Lead	
Building 460	Upton	11973	Unknown	Galvanized	No	Not Verified		1.5" < SL ≤ 2"	Galvanized	Field Inspection	Unknown	Business	No		1.5" < SL ≤ 2"	Non-Lead	
Building 461	Upton	11973	Unknown	Copper	No	Not Verified		1.5" < SL ≤ 2"	Copper	Field Inspection	Unknown	Other including Multiuse	No		1.5" < SL ≤ 2"	Non-Lead	
Building 462	Upton	11973	No	Known Other	No	Not Verified		Larger than 2"	Known Other	Field Inspection	No	Business	No		Larger than 2"	Non-Lead	
Building 463	Upton	11973	No	Known Other	No	Excavation		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 463	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 463	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 463	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 463	Upton	11973	No	Copper	No	Records		1.5" < SL ≤ 2"	Copper	Field Inspection	Unknown	Other including Multiuse	No		1.5" < SL ≤ 2"	Non-Lead	
Building 464	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Business	No		Larger than 2"	Non-Lead	
Building 464	Upton	11973	Unknown	Copper	No	Records		1.5" < SL ≤ 2"	Copper	Field Inspection	Unknown	Business	No		1.5" < SL ≤ 2"	Non-Lead	
Building 473	Upton	11973	No	Known Other	No	Not Verified		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 477	Upton	11973	No	Known Other	No	Not Verified		Larger than 2"	Known Other	Field Inspection	No	Business	No		Larger than 2"	Non-Lead	
Building 477	Upton	11973	Unknown	Galvanized	No	Records		1.5" < SL ≤ 2"	Galvanized	Field Inspection	Unknown	Business	No		1.5" < SL ≤ 2"	Non-Lead	
Building 477	Upton	11973	Unknown	Copper	No	Records		1.5" < SL ≤ 2"	Copper	Field Inspection	Unknown	Business	No		1.5" < SL ≤ 2"	Non-Lead	
Building 478	Upton	11973	No	Known Other	No	Not Verified		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 478	Upton	11973	Unknown	Copper	No	Not Verified		1.5" < SL ≤ 2"	Copper	Field Inspection	Unknown	Other including Multiuse	No		1.5" < SL ≤ 2"	Non-Lead	
Building 479	Upton	11973	No	Known Other	No	Not Verified		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 479	Upton	11973	No	Copper	No	Records		Larger than 2"	Copper	Field Inspection	Unknown	Other including Multiuse	No		Larger than 2"</		

Street Address	Town	Zip Code	Lead Gooseneck, Pigtail or Connector Currently Present?	Current Public Side SL Material ①	Was Public SL Material Ever Previously Lead?	Public SL Material Verification Method ①	Public SL Installation or Replacement Date	Public SL Size	Customer SL Material ①	Customer SL Material Verification Method ①	Lead Solder Present?	Building Type	POU or POE Treatment Present? ①	Customer SL Installation or Replacement Date	Customer SL Size	SL Category ①	Note
Building 480	Upton	11973	No	Copper	No	Records		Larger than 2"	Copper	Field Inspection	Unknown	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 480	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 480	Upton	11973	No	Copper	No	Records		Larger than 2"	Copper	Field Inspection	Unknown	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 488	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 488	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	Unknown	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 490	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	Unknown	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 490	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	Unknown	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 490	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 490	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	Unknown	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 490	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	Unknown	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 490	Upton	11973	No	Galvanized	No	Records		Larger than 2"	Galvanized	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 490	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 490	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 490	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 490	Upton	11973	No	Galvanized	No	Records		Larger than 2"	Galvanized	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	Out of service and isolated due to leak outside of building.
Building 493	Upton	11973	No	Known Other	No	Not Verified		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 494	Upton	11973	No	Copper	No	Not Verified		1.5" < SL ≤ 2"	Copper	Field Inspection	Unknown	Other including Multiuse	No		1.5" < SL ≤ 2"	Non-Lead	
Building 495	Upton	11973	No	Copper	No	Records		Up to 1"	Copper	Field Inspection	No	Other including Multiuse	No		Up to 1"	Non-Lead	
Building 498	Upton	11973	No	Copper	No	Records		Up to 1"	Copper	Field Inspection	No	Other including Multiuse	No		Up to 1"	Non-Lead	
Building 510	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 510	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	Unknown	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 510	Upton	11973	No	Known Other	No	Not Verified		Larger than 2"	Known Other	Field Inspection	Unknown	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 515	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	Unknown	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 515	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	Unknown	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 515	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 515	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 526	Upton	11973	No	Known Other	No	Not Verified		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 526	Upton	11973	No	Known Other	No	Not Verified		Larger than 2"	Known Other	Field Inspection	Unknown	Other including Multiuse	No		Larger than 2"	Non-Lead	Abandoned service.
Building 526	Upton	11973	Unknown	Galvanized	No	Records		Up to 1"	Galvanized	Field Inspection	Unknown	Other including Multiuse	No		Up to 1"	Non-Lead	
Building 528	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	Unknown	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 535	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	Unknown	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 535	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	Unknown	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 555	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	Unknown	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 555	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	Unknown	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 555	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	Unknown	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 560	Upton	11973	No	Copper	No	Records		1.5" < SL ≤ 2"	Copper	Field Inspection	No	Other including Multiuse	No		1.5" < SL ≤ 2"	Non-Lead	
Building 560	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 572	Upton	11973	No	Copper	No	Records		Up to 1"	Copper	Field Inspection	No	Other including Multiuse	No		Up to 1"	Non-Lead	Building 572 is supplied water from nearby Building 575.
Building 575	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	Unknown	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 598	Upton	11973	No	Copper	No	Records		1.5" < SL ≤ 2"	Copper	Field Inspection	No	Other including Multiuse	No		1.5" < SL ≤ 2"	Non-Lead	
Building 599	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 599	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 600	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 600	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 600	Upton	11973	No	Copper	No	Records		Larger than 2"	Copper	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 610	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 610	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	Unknown	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 610	Upton	11973	No	Copper	No	Records		1.5" < SL ≤ 2"	Copper	Field Inspection	Unknown	Other including Multiuse	No		1.5" < SL ≤ 2"	Non-Lead	
Building 624	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 630	Upton	11973	No	Copper	No	Records		Up to 1"	Copper	Field Inspection	Unknown	Other including Multiuse	No		Up to 1"	Non-Lead	
Building 631	Upton	11973	No	Copper	No	Not Verified		Up to 1"	Copper	Field Inspection	Unknown	Other including Multiuse	No		Up to 1"	Non-Lead	
Building 634	Upton	11973	No	Copper	No	Excavation		Up to 1"	Copper	Field Inspection	Unknown	Other including Multiuse	No		Up to 1"	Non-Lead	
Building 634	Upton	11973	No	Copper	No	Excavation		Up to 1"	Copper	Field Inspection	Unknown	Other including Multiuse	No		Up to 1"	Non-Lead	
Building 635	Upton	11973	No	Copper	No	Records		1" < SL ≤ 1.5"	Copper	Field Inspection	Unknown	Other including Multiuse	No		1" < SL ≤ 1.5"	Non-Lead	
Building 636	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 636	Upton	11973	No	Copper	No	Records		1.5" < SL ≤ 2"	Copper	Field Inspection	Unknown	Other including Multiuse	No		1.5" < SL ≤ 2"	Non-Lead	
Building 638	Upton	11973	No	Copper	No	Records		1.5" < SL ≤ 2"	Copper	Field Inspection	No	Other including Multiuse	No		1.5" < SL ≤ 2"	Non-Lead	
Building 650T	Upton	11973	No	Copper	No	Not Verified		Up to 1"	Copper	Field Inspection	No	Business	No		Up to 1"	Non-Lead	
Building 653	Upton	11973	No	Copper	No	Excavation		1.5" < SL ≤ 2"	Copper	Field Inspection	No	Other including Multiuse	No		1.5" < SL ≤ 2"	Non-Lead	
Building 653	Upton	11973	No	Copper	No	Excavation		Up to 1"	Copper	Field Inspection	No	Other including Multiuse	No		Up to 1"	Non-Lead	
Building 654	Upton	11973	No	Copper	No	Excavation		Up to 1"	Copper	Field Inspection	No	Other including Multiuse	No		Up to 1"	Non-Lead	
Building 655	Upton	11973	No	Copper	No	Excavation		Up to 1"	Copper	Field Inspection	No	Other including Multiuse	No		Up to 1"	Non-Lead	
Building 659	Upton	11973	No	Copper	No	Records		Up to 1"	Copper	Field Inspection	No	Other including Multiuse	No		Up to 1"	Non-Lead	
Building 668	Upton	11973	No	Copper	No	Excavation		Up to 1"	Copper	Field Inspection	No	Other including Multiuse	No		Up to 1"	Non-Lead	
Building 703	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	Yes	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 703	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 725	Upton	11973	No	Copper	No	Excavation		Larger than 2"	Copper	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 725	Upton	11973	No	Known Other	No	Excavation		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 725	Upton	11973	No	Known Other	No	Excavation		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 726	Upton	11973	No	Known Other	No	Not Verified		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 726	Upton	11973	No	Copper	No	Not Verified		1" < SL ≤ 1.5"	Copper	Field Inspection	Unknown	Other including Multiuse	No		1" < SL ≤ 1.5"	Non-Lead	
Building 727	Upton	11973	No	Known Other	No	Not Verified		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 727	Upton	11973	No	Copper	No	Not Verified		1" < SL ≤ 1.5"	Copper	Field Inspection	Unknown	Other including Multiuse	No		1" < SL ≤ 1.5"	Non-Lead	
Building 729	Upton	11973	No	Known Other	No	Not Verified		Larger than 2"	Known Other	Field Inspection	Unknown	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 734	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 734	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 735	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 735	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 741	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 741	Upton	11973	No	Copper	No	Records		Larger than 2"	Copper	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 741	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 742	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 742	Upton	11973	No	Copper	No	Records		Larger than 2"	Copper	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 742	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 742	Upton	11973	No	Copper	No	Records		Larger than 2"	Copper	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 743	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 743	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 744	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 744	Upton	11973	No	Copper	No	Records		Larger than 2"	Copper	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 744	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	

Street Address	Town	Zip Code	Lead Gooseneck, Pigtail or Connector Currently Present?	Current Public Side SL Material ①	Was Public SL Material Ever Previously Lead?	Public SL Material Verification Method ①	Public SL Installation or Replacement Date	Public SL Size	Customer SL Material ①	Customer SL Material Verification Method ①	Lead Solder Present?	Building Type	POU or POE Treatment Present? ①	Customer SL Installation or Replacement Date	Customer SL Size	SL Category ①	Note
Building 745	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 745	Upton	11973	No	Copper	No	Records		Larger than 2"	Copper	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 745	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 746	Upton	11973	No	Copper	No	Records		Larger than 2"	Copper	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 746	Upton	11973	No	Copper	No	Records		Larger than 2"	Copper	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 747	Upton	11973	No	Copper	No	Records		Larger than 2"	Copper	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 748	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 748	Upton	11973	No	Copper	No	Records		1.5" < SL ≤ 2"	Copper	Field Inspection	No	Other including Multiuse	No		1.5" < SL ≤ 2"	Non-Lead	
Building 749	Upton	11973	No	Copper	No	Not Verified		1" < SL ≤ 1.5"	Copper	Field Inspection	No	Business	No		1" < SL ≤ 1.5"	Non-Lead	
Building 750	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	Building 750 is abandoned.
Building 750	Upton	11973	No	Copper	No	Records		1" < SL ≤ 1.5"	Copper	Field Inspection	Unknown	Other including Multiuse	No		1" < SL ≤ 1.5"	Non-Lead	Building 750 is abandoned.
Building 751	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 754	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 754	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 801	Upton	11973	No	Galvanized	No	Not Verified		Larger than 2"	Galvanized	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 801	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	Unknown	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 815	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 815	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 815	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 815	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 817	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Business	No		Larger than 2"	Non-Lead	
Building 817	Upton	11973	No	Copper	No	Records		1.5" < SL ≤ 2"	Copper	Field Inspection	No	Business	No		1.5" < SL ≤ 2"	Non-Lead	
Building 817	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Business	No		Larger than 2"	Non-Lead	
Building 820	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 820	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 830	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 832	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 832	Upton	11973	No	Copper	No	Records		1" < SL ≤ 1.5"	Copper	Field Inspection	No	Other including Multiuse	No		1" < SL ≤ 1.5"	Non-Lead	
Building 835	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 836	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 836	Upton	11973	No	Copper	No	Records		1" < SL ≤ 1.5"	Copper	Field Inspection	No	Other including Multiuse	No		1" < SL ≤ 1.5"	Non-Lead	
Building 855	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 855	Upton	11973	No	Copper	No	Records		1" < SL ≤ 1.5"	Copper	Field Inspection	No	Other including Multiuse	No		1" < SL ≤ 1.5"	Non-Lead	
Building 860	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 860	Upton	11973	No	Copper	No	Records		Larger than 2"	Copper	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 865	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 865	Upton	11973	No	Copper	No	Records		1.5" < SL ≤ 2"	Copper	Field Inspection	No	Other including Multiuse	No		1.5" < SL ≤ 2"	Non-Lead	
Building 870	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	Out of service due to leak.
Building 870	Upton	11973	No	Copper	No	Records		1" < SL ≤ 1.5"	Copper	Field Inspection	No	Other including Multiuse	No		1" < SL ≤ 1.5"	Non-Lead	
Building 901	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	Unknown	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 901A	Upton	11973	No	Known Other	No	Not Verified		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 901A	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	Unknown	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 902	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 902	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	Unknown	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 902	Upton	11973	No	Galvanized	No	Records		Larger than 2"	Galvanized	Field Inspection	Unknown	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 902	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	Unknown	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 902	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	Unknown	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 902	Upton	11973	No	Known Other	No	Records		larger than 2"	Copper	Field Inspection	Unknown	Other including Multiuse	No		1.5" < SL ≤ 2"	Non-Lead	
Building 902	Upton	11973	Unknown	Galvanized	No	Records		1.5" < SL ≤ 2"	Galvanized	Field Inspection	Unknown	Other including Multiuse	No		1.5" < SL ≤ 2"	Non-Lead	
Building 904	Upton	11973	Unknown	Copper	No	Not Verified		1.5" < SL ≤ 2"	Copper	Field Inspection	Unknown	Other including Multiuse	No		1.5" < SL ≤ 2"	Non-Lead	Building 904 is abandoned and planned to be demolished.
Building 905	Upton	11973	No	Copper	No	Records		1.5" < SL ≤ 2"	Copper	Field Inspection	Unknown	Other including Multiuse	No		1.5" < SL ≤ 2"	Non-Lead	
Building 906	Upton	11973	No	Copper	No	Records		Up to 1"	Copper	Field Inspection	Unknown	Other including Multiuse	No		Up to 1"	Non-Lead	
Building 907	Upton	11973	No	Known Other	No	Not Verified		1.5" < SL ≤ 2"	Known Other	Field Inspection	No	Other including Multiuse	No		1.5" < SL ≤ 2"	Non-Lead	
Building 907	Upton	11973	No	Copper	No	Not Verified		Larger than 2"	Copper	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 911	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	Unknown	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 911	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	Unknown	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 911	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	Unknown	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 911	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	Unknown	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 911	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	Unknown	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 911	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	Unknown	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 911	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	Unknown	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 912	Upton	11973	No	Known Other	No	Not Verified		Larger than 2"	Known Other	Field Inspection	Unknown	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 912	Upton	11973	No	Known Other	No	Not Verified		Larger than 2"	Known Other	Field Inspection	Unknown	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 912	Upton	11973	No	Known Other	No	Not Verified		Larger than 2"	Known Other	Field Inspection	Unknown	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 912	Upton	11973	No	Copper	No	Not Verified		Up to 1"	Copper	Field Inspection	Unknown	Other including Multiuse	No		Up to 1"	Non-Lead	
Building 913S	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 913S	Upton	11973	No	Copper	No	Not Verified		1.5" < SL ≤ 2"	Copper	Field Inspection	No	Other including Multiuse	No		1.5" < SL ≤ 2"	Non-Lead	
Building 914	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 914	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	Unknown	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 918	Upton	11973	No	Known Other	No	Not Verified		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 918	Upton	11973	No	Copper	No	Not Verified		Up to 1"	Copper	Field Inspection	Unknown	Other including Multiuse	No		Up to 1"	Non-Lead	
Building 919	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 919A	Upton	11973	No	Copper	No	Not Verified		Larger than 2"	Copper	Field Inspection	Unknown	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 919B	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 919H	Upton	11973	No	Copper	No	Not Verified		1.5" < SL ≤ 2"	Copper	Field Inspection	No	Other including Multiuse	No		1.5" < SL ≤ 2"	Non-Lead	
Building 922	Upton	11973	No	Known Other	No	Not Verified		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 922	Upton	11973	No	Known Other	No	Not Verified		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 923	Upton	11973	No	Copper	No	Records		Larger than 2"	Copper	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 923	Upton	11973	No	Known Other	No	Not Verified		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 924	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 924	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 925	Upton	11973	No	Known Other	No	Not Verified		Larger than 2"	Known Other	Field Inspection	Unknown	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 926	Upton	11973	No	Copper	No	Not Verified		1.5" < SL ≤ 2"	Copper	Field Inspection	Unknown	Other including Multiuse	No		1.5" < SL ≤ 2"	Non-Lead	
Building 926	Upton	11973	No	Known Other	No	Not Verified		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 927	Upton	11973	No	Known Other	No	Not Verified		Larger than 2"	Known Other	Field Inspection	Unknown	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 929	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	Unknown	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 930	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 930	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 930	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse	No		Larger than 2"	Non-Lead	
Building 931	Upton	11973	No	Copper	No	Records		1.5" < SL ≤ 2"	Copper	Field Inspection	Unknown	Other including Multiuse	No		1.5" < SL ≤ 2"	Non-Lead	

Street Address	Town	Zip Code	Lead Gooseneck, Pigtail or Connector Currently Present?	Current Public Side SL Material ⓘ	Was Public SL Material Ever Previously Lead?	Public SL Material Verification Method ⓘ	Public SL Installation or Replacement Date	Public SL Size	Customer SL Material ⓘ	Customer SL Material Verification Method ⓘ	Lead Solder Present?	Building Type	POU or POE Treatment Present? ⓘ	Customer SL Installation or Replacement Date	Customer SL Size	SL Category ⓘ	Note
Building 933	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse No			Larger than 2"	Non-Lead	
Building 933	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse No			Larger than 2"	Non-Lead	
Building 935	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Business	No		Larger than 2"	Non-Lead	
Building 935	Upton	11973	No	Copper	No	Records		1.5" < SL ≤ 2"	Copper	Field Inspection	Unknown	Business	No		1.5" < SL ≤ 2"	Non-Lead	
Building 936	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse No			Larger than 2"	Non-Lead	
Building 938	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse No			Larger than 2"	Non-Lead	
Building 938	Upton	11973	No	Copper	No	Records		1" < SL ≤ 1.5"	Copper	Field Inspection	Unknown	Other including Multiuse No			1" < SL ≤ 1.5"	Non-Lead	
Building 939	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse No			Larger than 2"	Non-Lead	
Building 939	Upton	11973	No	Copper	No	Records		1.5" < SL ≤ 2"	Copper	Field Inspection	Unknown	Other including Multiuse No			1.5" < SL ≤ 2"	Non-Lead	
Building 940	Upton	11973	No	Known Other	No	Not Verified		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse No			Larger than 2"	Non-Lead	
Building 945	Upton	11973	No	Copper	No	Records		1" < SL ≤ 1.5"	Copper	Field Inspection	Unknown	Other including Multiuse No			1" < SL ≤ 1.5"	Non-Lead	
Building 957	Upton	11973	No	Copper	No	Records		1.5" < SL ≤ 2"	Copper	Field Inspection	No	Other including Multiuse No			1.5" < SL ≤ 2"	Non-Lead	
Building 958	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse No			Larger than 2"	Non-Lead	
Building 958	Upton	11973	No	Copper	No	Records		1.5" < SL ≤ 2"	Copper	Field Inspection	No	Other including Multiuse No			1.5" < SL ≤ 2"	Non-Lead	
Building 974	Upton	11973	No	Copper	No	Records		1.5" < SL ≤ 2"	Copper	Field Inspection	No	Other including Multiuse No			1.5" < SL ≤ 2"	Non-Lead	
Building 975	Upton	11973	No	Copper	No	Records		1.5" < SL ≤ 2"	Copper	Field Inspection	Unknown	Other including Multiuse No			1.5" < SL ≤ 2"	Non-Lead	
Building 1000P	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	Unknown	Other including Multiuse No			Larger than 2"	Non-Lead	
Building 1002A	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse No			Larger than 2"	Non-Lead	
Building 1002A	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	Unknown	Other including Multiuse No			Larger than 2"	Non-Lead	
Building 1004A	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse No			Larger than 2"	Non-Lead	
Building 1004A	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	Unknown	Other including Multiuse No			Larger than 2"	Non-Lead	
Building 1004B	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse No			Larger than 2"	Non-Lead	
Building 1004B	Upton	11973	No	Copper	No	Records		1.5" < SL ≤ 2"	Copper	Field Inspection	No	Other including Multiuse No			1.5" < SL ≤ 2"	Non-Lead	
Building 1005H	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse No			Larger than 2"	Non-Lead	
Building 1005H	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	Unknown	Other including Multiuse No			Larger than 2"	Non-Lead	
Building 1005P	Upton	11973	No	Copper	No	Records		Larger than 2"	Copper	Field Inspection	Unknown	Other including Multiuse No			Larger than 2"	Non-Lead	
Building 1005R	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse No			Larger than 2"	Non-Lead	
Building 1005R	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	Unknown	Other including Multiuse No			Larger than 2"	Non-Lead	
Building 1005S	Upton	11973	No	Known Other	No	Records		Larger than 2"	Known Other	Field Inspection	No	Other including Multiuse No			Larger than 2"	Non-Lead	Building 1005S is supplied water from adjacent Building 1005R.
Building 1005S	Upton	11973	No	Copper	No	Records		Larger than 2"	Copper	Field Inspection	Unknown	Other including Multiuse No			Larger than 2"	Non-Lead	Building 1005S is supplied water from adjacent Building

Information and Instructions

Name your inventory as LSLI_NYPWSID#. For example:
LSLI_NY1234567

Lead Service Line Inventory Template Workbook

- The Service Line Inventory Template is to be filled out with one row for each service line.
- Columns with headings in blue are required or mandatory entries to be considered complete.
- Headers with an ⓘ symbol will display additional information if clicked on.
- The options for all drop down response columns are listed below.

Inventory Summary Workbook

- Do not fill out Section III, "Summary of Inventory." The section will be automatically filled based on information provided in the LSL Template workbook.

Tabs	Description
Service Line Inventory Template	To be filled out with service line information
Inventory Summary Form	Summary of data from Service Line Inventory Worksheet

Public-side Service Line Information Keys

Lead Gooseneck, Pigtail or Connector Currently Present?	Current Public Side SL Material	Was Public SL Material Ever Previously Lead?	Public SL Material Verification Method	Public SL Size
Yes	Lead including lead-lined galvanized	Yes	Records	Up to 1"
No	Copper	No	Field Inspection	1" < SL ≤ 1.5"
Unknown	Galvanized	Unknown	Excavation	1.5" < SL ≤ 2"
	Plastic		Sequential Sampling	Larger than 2"
	Known Other		Statistical Analysis/Predictive Model	Unknown
	Unknown but could be lead		Other	
	Unknown but unlikely lead		Not Verified	
	Unknown			

Customer Side Service Line Information Keys

Customer SL Material	Customer SL Material Verification Method	Lead Solder Present?	Building Type	POU or POE Treatment Present?	Customer SL Size
Lead including lead-lined galvanized	Records	Yes	Single Family	Yes	Up to 1"
Copper	Field Inspection	No	Multi Family	No	1" < SL ≤ 1.5"
Galvanized	Customer Identification with Photo or Other Verification	Unknown	School or Childcare	Unknown	1.5" < SL ≤ 2"
Plastic	Excavation		Business		Larger than 2"
Known Other	Sequential Sampling		Other including Multiuse		Unknown
Unknown but could be lead	Statistical Analysis/Predictive Model				
Unknown but unlikely lead	Other				
Unknown	Not Verified				

Entire Service Line Inventory

Categories
SL Category
Lead
GSLRR
Non-Lead
Unknown - Lead Status Unknown